

## GRAPHICOL

Iron foundries use microcrystalline graphite as a recarburizer for raising the carbon content of iron melted in electrical furnaces

### RECARBURIZER

		<b>GRAPHICOL 90</b>	<b>GRAPHICOL 97</b>	<b>GRAPHICOL 99</b>
CARBON CARBONIO	[%] MIN	90	97	99
ASH CENERI CEINDRES	[%] MAX	7,0	2,0	0,8
HUMIDITY UMIDITA' HUMIDITE'	[%] MAX	0,5	0,5	0,5
VOLATILE SOSTANZE VOLATILI VOLAILLES	[%] MAX	2,0	1,0	0,05
SULPHUR ZOLFO SULPHURE	[%] MAX	0,8	0,6	0,05
GRAIN SIZE GRANULOMETRIA GRANULOMETRIE	[mm]	1-4	1-4	1-4